



We approach the solution of the AC unit commitment (UC) problem using a three-step strategy. First, we solve a linearized UC version of the original AC UC problem to obtain an initial solution and to identify potentially congested lines. Second, we solve a second-order-conic relaxation of the original AC UC

